

Map ID  
Direction  
Distance  
Elevation

MAP FINDINGS

EDR ID Number  
EPA ID Number

JE1299  
North  
> 1  
1.665 mi.  
8792 ft.

CONED MANHOLE #147586  
1781 WEST 3RD STREET  
BROOKLYN, NY

NY Spills S106699590  
N/A

Site 1 of 2 in cluster JE

Relative:  
Higher

Actual:  
25 ft.

SPILLS:

Name: CONED MANHOLE #147586  
Address: 1781 WEST 3RD STREET  
City,State,Zip: BROOKLYN, NY  
Spill Number/Closed Date: 0406997 / 2004-11-19  
Facility ID: 0406997  
Facility Type: ER  
DER Facility ID: 238099  
Site ID: 294212  
DEC Region: 2  
Spill Cause: Unknown  
Spill Class: D4  
SWIS: 2401  
Spill Date: 2004-09-23  
Investigator: GDBREEN  
Referred To: Not reported  
Reported to Dept: 2004-09-24  
CID: 444  
Water Affected: Not reported  
Spill Source: Unknown  
Spill Notifier: Responsible Party  
Cleanup Ceased: Not reported  
Cleanup Meets Std: False  
Last Inspection: Not reported  
Recommended Penalty: False  
UST Trust: False  
Remediation Phase: 0  
Date Entered In Computer: 2004-09-24  
Spill Record Last Update: 2004-11-19  
Spiller Name: Not reported  
Spiller Company: Not reported  
Spiller Address: Not reported  
Spiller Company: 001  
Contact Name: ERT DESK  
DEC Memo: "Employee REPORTS, APPX one PT OF UNKNOWN OIL ON APPX one GAL OF WATER IN THE STRUCTURE. NO SEWERS, WATERWAYS OR PRIVATE PROPERTY INVOLVED. SPILL IS CONTAINED TO THE STRUCTURE. THERE IS NO VISUAL WATER MOVEMENT, IT IS STANDING STILL AND HE IS UNABLE TO VISUALIZE ANY SUMPS OR SUBSTANTIAL cracks in the structure. Environmental tag 44576 WAS HUNG, LIQUID SAMPLE FOR PCBs TAKEN PCB RESULTS < 1.0 PPM, LSN 04-07628-001. 9/24/04 00:50 HRS. -- A. GLODOWSKI OF BROOKLYN ENV OPS ON LOCATION FOR CLEANUP AND REPORTS FOUND CAR OVER HOLE. CLEANUP TO BE ATTEMPTED AGAIN IN MORNING. UPDATE: 9/25/04 - 1030 S. RAFT - ENV. OPS., REPORTS CLEANUP COMPLETED BY DOUBLE WASHING STRUCTURE WITH BULLDOG. NO SUMPS. TAG # 44576 REMOVED."  
Remarks: "1 QUART ON 1 GALLON IN A MANHOLE: DUE TO UNABLE TO GET TO IT IT IS COMING OFF 24 HOUR CLOCK: NO RESOURCES AVAILABLE; CONED # 155508: NO TO 5 QUESTIONS: "

All Materials:

Site ID: 294212  
Operable Unit ID: 889592  
Operable Unit: 01  
Material ID: 484838

Map ID  
Direction  
Distance  
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number  
EPA ID Number

Material Code:	0066A
Material Name:	unknown petroleum
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.00
Units:	Not reported
Recovered:	.00
Oxygenate:	Not reported